TOWNHOUSE AT 107 & 105 BANK STREET



Community Board 2 Landmarks Committee


May 16, 2022



HIGGINS QUASEBARTH & PARTNERS LLC ROUNDSQUARE DEVELOPMENT LLC



Project Location: Greenwich Village - Historic District



105 & 107 Bank Street - Block



105 & 107 Bank Street (right to left)




105 - 111 Bank Street, 1932 (NYPL)




105 - 111 Bank Street, 1969 (LPC Designation Photo)

107 BANK STREET


NEW YORK, NEW YORK



105 - 111 Bank Street, 2019




1854





1895



1956

1921





44-46 Horatio (Approved 2015)



75 Bedford



65 Horatio Street (Approved 2020)




109 Bank Street (Approved 2020)



109 Bank Street (Approved 2020)



109 Waverly Place (Approved 2008)



22 Bank (Approved 2019)




146 Waverly Place (Approved 2014)



18 Commerce Street



Existing 107 and 105 Bank



Proposed 107 and 105 Bank



Existing rear of 105 and 107 Bank



Proposed rear of 105 and 107 Bank




107 and 105 Bank - Current Street Elevation



105 and 107 Bank - Current Rear Elevation

105 BANK

107 BANK








105 Bank

107 Bank

105 and 107 Bank - Current Rear Conditions

105 and 107 Bank - Rear Addition Current Conditions



111 109 107 105



1904 Sanborn Map

Current Conditions (since approx. 1950's)

Proposed Design

Extensions



Main Volume










O 107 Bank St. (Lot 34)

105 Bank St. (Lot 33)

N








1. View of Site

2. View down Bank St.

3. View down Bank St.



4. View down Bank St.





1. View of Street Facade



4. View from Greenwich Ave corner



2. View of 107 Areaway




5. View of 105 Areaway



3. 107 railing



6. 105 railing



Existing Site Map










Existing Elevation

Proposed Elevation






1. Brownstone

Material: Existing brownstone to be restored as per LPC. New base material for 105 Bank areaway pending probe survey. Intend to match color and finish of existing base at 111 Bank.



2. Brick **Material:** Existing brick to be restored as per LPC. Any new brick to match existing.




3. Cornices Material: Solid Wood Color/Finish: Existing and proposed cornices to be Benjamin Moore color Silhouette, AF-655



4. Penthouse Material Material: Metal clad. Color/Finish: Benjamin Moore, Kennebunkport Green, HC-123. Kynar finish.



5. Penthouse Windows and Doors Manufacturer: Marvin (Custom Wood) Color/Finish: Benjamin Moore, Kennebunkport Green, HC-123.



6. Windows and Doors Manufacturer: Marvin (Custom Wood) Material: Wrought iron painted Color/Finish: Benjamin Moore, Black Forest Green, HC-187.



7. Metal Railings

Color/Finish: Benjamin Moore, Iron 2120-20.



8. Front Entrance Door Material: Existing Solid Wood Finish/Color: Existing wooden door to be restored and refurbished. Stain to match existing.










Existing 105 areaway window



Proposed 105 areaway window



Existing 107 areaway staircase



107 Existing areaway



Existing 107 areaway door



Proposed 107 areaway door



107 Proposed areaway



Existing 105 areaway door



Existing 105 areaway door



Existing 105 areaway door




Proposed 105 areaway window



Proposed 107 areaway door



Proposed 105 areaway window



105 Existing areaway



105 Proposed areaway



1940's Photo



1970's Photo



Current Conditions



Proposed Entry - to restore current conditions



Existing entablature




Existing overdoor



Existing capital



Existing door frame bracket detail



Existing 107 front door



Proposed 107 front door







107 - 105 Bank, 1932 (nypl)



107 - 105 Bank historic cornice, 1932 (nypl)



107 - 105 Bank, proposed cornice





View of street with existing conditions


View of street with proposed design



Historic image of previous townhouse at alley (103 Bank - demolished)



1. View of Existing 105 Alley




3. View of Existing 105 Alley




2. View of Existing 105 Alley fence



4. View of Existing 105 Alley







1. View of 105 Rear Facade.



4. View of 107 Rear Facade.




2. View of 105 Rear Garden.



5. View of 107 Rear Garden.



3. View of 105 and 107 Rear Facades.



Key Plan













Existing rear of 105 and 107 bank



Proposed rear of 105 and 107 bank


1. Window Heads and Sils

Material: Existing brownstone to be restored as per LPC. New base material for 105 Bank areaway pending probe survey. Intend to match color and finish of existing base at 111 Bank..




2. Brick

Color/Finish: Brick to be savaged where possible and remain where noted. New brick to match existing rear brick at 107 Bank.




3. Penthouse and Bay

Material: Metal clad Color/Finish: Benjamin Moore, Kennebunkport Green, HC-123.




5. Windows and Doors

Manufacturer: Marvin (Custom Wood) Color: Benjamin Moore, Kennebunkport Green HC-123




6. Metal Porch, and Stair

Color/Finish: Wrought iron painted, Benjamin Moore, Kennebunkport Green, HC-123





7. Metal Railings


Color/Finish: Wrought iron painted Rails, Benjamin Moore Kendall Charcoal - HC-166


















Proposed Massing








3.



1.



4.






Visibility from bank street



View of proposed design






Visibility from bank street



View of proposed design






Visibility from bank street



View of proposed design







Visibility from bank street



View of proposed design.






Visibility from Bank Street.



View of proposed design.






Visibility from Bethune St.



View of proposed from Bethune St.





Existing 107 and 105 bank



Proposed 107 and 105 bank





Existing rear of 105 and 107 bank





Proposed rear of 105 and 107 bank





















EXISTING STUCCO

EXISTING BRICK UNDER STUCCO