### **SHEET LIST**

#### Project Background

- Site Location
- Site Context
- Tax Photographs
- Present Day Elevation Views
- Context Elevation Views
- Sanborn Maps & Block Plan
- **Existing Conditions**

### Relevant Projects

- 11) 340 West 12th Renovation
- 12) LPC Approved Precedents

### **Elevations**

- 13) Elevation Scope
- 16) Existing & Proposed Street Elevation17) Existing & Proposed Rear Elevation

### **Property Sections**

- 18) Existing Long Section19) Proposed Long Section
- 20) Existing & Proposed Cross Section

### Floor Plans

- 21) Existing & Proposed Floors Plans (Lower Levels)
  23) Existing & Proposed Floors Plans (Upper Levels)



## 338 WEST 12TH STREET

LANDMARKS PRESERVATION COMMISSION

JULY 13, 2023




HIGGINS QUASEBARTH & PARTNERS LLC

KAREN THOMAS ASSOCIATES, INC.

View of 338 West 12th Street, (RAMSA)

# Greenwich Village



Greenwich Village Historic District Map







336 Tax Photo. NYC Department of Records)



338 1940 Tax Photo. NYC Department of Records)



340 1940 Tax Photo. NYC Department of Records)




Street Elevation (RAMSA, 2023)




Rear Elevation (RAMSA, 2023)



Rear Elevations (left to right: 340, 338, 336) (RAMSA, 2023)







Sanborn Map 1899 (Library of Congress)


Sanborn Map 1955 (Library of Congress)

### BETHUNE STREET





Horsewalk Entries, 336 (left) and 338 (right) (RAMSA, 2023)



340 Horsewalk Entry (RAMSA, 2023)





Rear Elevation (HQP, 2023)




Rear Elevation, Garden Level (HQP, 2023)



Joint Detail (HQP, 2023)

Expansion joint between 338 and 340 W. 12th; the historic facade of 338 is visibly out of plumb.



Rear Window (HQP, 2023)
Detail of the brick between the Parlor and Second floors, showing step cracking.



Detail of the brick at the Garden level showing significant spalling and material loss, and efflorescence.



Detail at Parlor Window, showing visible circular abrasions



Brick & Mortar Decay (HQP, 2023)

Detail of brick at the rear facade showing typical conditions, including abrasions from a mechanical grinder, spalling and material loss, efflorescence, and improper mortar type.



Roof (HQP, 2023), Looking Southeast



Fourth Floor Deck (RAMSA, 2023)




Roof (HQP, 2023), Looking West



Fourth Floor Deck (RAMSA, 2023)











































N LE: 1/8" = 1'-0"

