

## CITY OF NEW YORK

## MANHATTAN COMMUNITY BOARD FOUR

424 West 33<sup>rd</sup> Street, Suite #580 New York, NY 10001

> tel: 212-736-4536 www.nyc.gov/mcb4

JEFFREY LEFRANCOIS

Chair

JESSE R. BODINE District Manager

August 9, 2022

Rick Cotton
Executive Director
Port Authority of New York & New Jersey (PANYNJ)
4 World Trade Center
150 Greenwich Street, 22<sup>nd</sup> Floor
New York, NY 10006

Ed Pincar Manhattan Borough Commissioner NYC Department of Transportation (DOT) 59 Maiden Lane, 37<sup>th</sup> Floor New York, NY 10038

Re: Safety Concerns at the 42<sup>nd</sup> Street and Dyer Avenue Pedestrian Crossing

Dear Executive Director Cotton and Borough Commissioner Pincar,

Manhattan Community Board Four (MCB4) asks your coordinated assistance in resolving the dangerous conditions for pedestrians at the T-intersection of Dyer Avenue and 42<sup>nd</sup> Street. Currently, the intersection has three lanes for drivers exiting Dyer Avenue to make either left or right turns, and one contraflow lane for buses to make right turns onto Dyer Avenue. Pedestrians must therefore face three conditions across four lanes; drivers exiting the tunnel often fail to adjust to city regulations such as the 25mph speed limit, pedestrian rights-of-way, and no turn on red.

We heard from residents of MIMA, a 900-unit residential building. Several have suffered injuries while crossing the intersection. There is also a 41-story residential building on the SE corner, and theatres on both sides of Dyer Avenue. 42<sup>nd</sup> Street is one of the most highly trafficked pedestrian corridors in our district.

MCB4 at its July 27<sup>th</sup> Full Board meeting, voted by 39 in favor, 0 opposed, 0 abstaining, and 0 present but not eligible to vote, to ask you to consider any and all of the following solutions:

- Divert eastbound traffic to West 40<sup>th</sup> Street and/or divert westbound traffic to West 41<sup>st</sup> Street. Doing both would allow for a plaza to be created between 41<sup>st</sup> and 42<sup>nd</sup> Streets on Dyer Avenue, with one contraflow lane for buses.
- Extend the bus lane markings on West 42<sup>nd</sup> Street to Dyer Avenue and reduce the number of lanes turning east to one on Dyer Avenue, to match the capacity on West 42<sup>nd</sup> Street.
- Review and adjust signal timing to provide pedestrians with more time for crossing, up to and including the option of a Barnes Dance configuration.

Thank you for your continued cooperation as we seek to make our district safe for both residents and visitors.

Sincerely,

Jeffrey LeFrancois

Chair

Manhattan Community

Sfley C. le Ermon

Board 4

Christine Berthet

Mer Met

Co-chair

**Transportation Planning** 

Committee

Dale Corvino

Co-chair

**Transportation Planning** 

Committee