




257 WEST 4TH STREET RESIDENCE





EXAMPLE: 3C  
3: NUMBER OF FLOORS ABOVE GRADE  
C: CELLAR FLOOR



EXISTING FRONT ELEVATION



PROPOSED FRONT ELEVATION







EXISTING REAR ELEVATION



PROPOSED REAR ELEVATION




EXISTING SECTION




PROPOSED SECTION


EXISTING CELLAR



PROPOSED CELLAR




EXISTING 1ST FLOOR



WEST 4TH ST.  
(44'-0" NARROW)


PROPOSED 1ST FLOOR



WEST 4TH STREET




EXISTING ROOF FLOOR



WEST 4TH ST.  
(44'-0" NARROW)

PROPOSED ROOF FLOOR



WEST 4TH STREET





BULKHEAD MOCKUP

CHIMNEY MOCKUP

RAILING MOCKUP



PROPOSED BULKHEAD MATERIAL: WOOD  
COLOR: BLACK GREEN FOREST



PROPOSED BULKHEAD MATERIAL: WOOD  
COLOR: BLACK GREEN FOREST







CHIMNEY MOCKUP



CHIMNEY MONTAGE





CHIMNEY & BULKHEAD MOCKUP (VIEW FROM SOUTH)



CHIMNEY & BULKHEAD MONTAGE





CHIMNEY & BULKHEAD MOCKUP (MAXIMUM VISIBILITY FROM SOUTH)

CHIMNEY & BULKHEAD MONTAGE





CHIMNEY & RAILING MOCKUP (VIEW FROM NORTH)



CHIMNEY & RAILING MONTAGE





PHOTOS TAKEN FROM ROOF OF 257 WEST 4TH STREET (JANUARY)



PHOTOS TAKEN FROM ROOF OF 257 WEST 4TH STREET (JULY)





PHOTOS TAKEN FROM ROOF OF 29 CHARLES STREET (JULY)



RENDERING





PHOTOS TAKEN FROM ROOF OF 29 CHARLES STREET (JULY)



RENDERING





257 WEST EXISTING REAR YARD

DETERIORATED RETAINING WALL



257 WEST EXISTING REAR YARD

REPAIRED RETAINING WALL