


149 Mercer, existing conditions



149 Mercer, proposed

DRAFT - DOOR TO BE UPDATED

SOHO-CAST IRON HISTORIC DISTRICT



SoHo-Cast Iron Historic District, designated boundaries.



149 Mercer Block Plan







149 Mercer, ca. 1940 Tax Photograph [NY Archives]








2022, existing conditions







149 Mercer Street, at center (1940, NYC Tax Photograph)



1930 Bromley Insurance Map



165-167 Mercer Street (1940, NYC Tax Photograph)




171 Mercer Street (1940, NYC Tax Photo)



North on Mercer from Prince (1934, Municipal Archives)


DRAFT - UPDATE WITH HI-RES



Firemen's Hall, ADDRESS (1905, MCNY)













Mercer Street, applied texture glazing



Mercer Street, typical "back-of-house" conditions



Mercer Street, historic shuttered windows



















Residential entry doors.



Residential entry, granite sill.



Storefront overview, looking southwest.



Storefront base, granite sill.



Retail entry doors.





Retail entry header and lighting detail.


















































LEASELINE EXTERIOR 10'-2 1/4" AFF T.O. STOREFRONT 8'-8" AFF B.O. SIGN BAND INTERIOR EXISTING BRICK TO REMAIN 1/8" THK. BLACK STEEL-CLADDING AT SOFFIT [MT-1] UNDISTURBED (LANDMARKED FACADE) RECESSED U-CHANNEL WITH
GASKET/CAULKING AT TOP AND
BOTTOM TO RECEIVE GLAZING SINGLE SWING DOOR WITH THERMALLY BROKEN INSULATED GLASS ASSEMBLY TO MATCH STOREFRONT ASSEMBLY GL-1 AND 2" THICK BLACK FRAME CUSTOM BLACK CTD. STEEL -DOOR HANDLE, TBD DBL LAMINATED ETCHED GLASS
WITH TRANSLUCENT TINTED INTERLAYER, GLASS PANEL

[GL-1] 1/8" THK. BLACK CTD. STEEL METAL CLADDING [MT-2] AT RAMP FLOORING STEEL T-ANGLE WITH BLOCKING 0'-0" AFF T.O. INTERIOR FINISH BOLTED DOWN TO SUPPORT STOREFRONT STRUCTURE MT-2 - 0'-2 3/4" AFF 2'-5 3/4" SIDEWALK LEVEL


ENTRY VESTIBULE ELEVATION (RIGHT)




ENTRY VESTIBULE ELEVATION (LEFT)












Storefront steel & perforated signage steel



Entry floor sample, textured steel





TO BE UPDATED WITH NEW ENTRY DOOR





APPENDIX





